Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	"20020133265".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/03/30 23:23
L2	0	"20020133265".pn. and substantial\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/03/30 23:43
L3	2	"20020133265".pn. and (substant\$6 or independent\$4 or separat\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/03/30 23:43
L4	10	("5467293" "5815154" "6120171" " 6219049" "6219055" "5434791" "56 59493" "6356800" "6430455" "2002 0133264").PN.	US-PGPUB; USPAT	OR	ON	2005/03/30 23:52
L5	4	("5184426" "5691909" "5793647" "6341996").pn.	US-PGPUB; USPAT	OR	ON	2005/03/30 23:52
L6	7969	700/18,19,29,30,83,86,95-98, 105-107,146,159,160,181-187,190, 192.ccls. or 703/1.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/03/30 23:52
L7	745	345/420.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	O R	ON	2005/03/30 23:53
L8	347	((700/18,19,29,30,83,86,95-98, 105-107,146,159,160,181-187,190, 192.ccls. or 703/1.ccls.) or 345/420. ccls.) and ((virtual\$2 or simulat\$4 or emulat\$4 or model\$4 or CAD or CAD/CAM) with (machin\$4 or drill\$4 or mill\$4 or stamp\$4 or cut\$4 or bor\$5 or NC or CNC or (numeric\$4 near2 control\$4))) and ((virtual\$2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/03/30 23:53
		or simulat\$4 or emulat\$4 or model\$4 or CAD or CAD/CAM) near2 (original\$2 or base or premise or template))				

L9	8612	(700/18,19,29,30,83,86,95-98, 105-107,146,159,160,181-187,190,	US-PGPUB; USPAT;	OR	ON	2005/03/30 23:53
		192.ccls. or 703/1.ccls.) or 345/420.	EPO; JPO;]	
		ccls.	DERWENT;			
	l ,		IBM_TDB			